



Mark both
sides as
shown before
cutting





View after
cutting





Mark both
sides and
cut




Use hydraulic
press as
shown



7.5cm



Weld both
sides



Cut here in
case you
need it



Place all electronics into the fender
*Original electrical caddy is not used

Final
view